

PortaMelt™

ELECTRIC ARC BUTTON REMELT FURNACE

The customizable Cianflone PortaMelt[™] Electric Arc Button Remelt Furnace makes alloy research easier.





PRODUCT OVERVIEW

The PortaMeltTM Arc Button Remelt Furnace is used to prepare solid metal samples from odd shape materials. This includes drillings, lathe turnings, welding wire, powder, etc.

The customizable Cianflone PortaMeltTM Electric Arc Button Remelt Furnace will:

- Melt alloys up to 3600° F.
- The sample charge can be slugs, cuttings, drillings, powders, etc.
- Violence of the arc provides mixing action
- A charge of 50 grams of steel will provide a sample of 1-1/4 inch diameter and approximately 1/4 inch thick.
- Its primary use is for the preparation of spectrographic samples

The PortaMeltTM offers a low cost, low maintenance solution that produces homogeneous sample buttons for spectrographic elemental analysis and alloy research.



SPECIFICATIONS

- Melting times are one minute or less
- Anodes available in carbon graphite and tungsten
- Water-cooled copper crucible is tiltable for easy sample removal
- Customizable if required
- Vacuum vs open-air sample production (sample produced under gas atmosphere.)
- High temperature (3600°F)



COMMON INDUSTRY APPLICATIONS

- Welding, Recycling, Scrap Metal
- Abrasives / Cleaning
- Purity Measurement
- Manufacturing
- Quality Control and Inbound Purchasing
- Powder Melting
- High Purity Melts



PortaMeIt[™]

ELECTRIC ARC BUTTON REMELT FURNACE

WORLDWIDE APPLICATION

Companies worldwide depend on Cianflone Scientific to provide efficient and effective portable elemental analysis, coating thickness measurements and sample preparation.



PortaMeltTM SPECIFICATIONS

Range of metals and alloys that can be remelted	METAL TYPE Aluminum Copper Steel Titanium Chromium Alloys	TEMPERATURE 1220° F 1983° F 2600° F - 2800° F 3040° F 3380° F Up to 3600° F
Copper Crucible Loads	LOAD IN GRAMS 50 72 86 100	BUTTON DIAMETER 1-1/4" 1-1/2" 1-5/8" 1-3/4"
Melting Time	Most high temperature alloys are in the order of 50-60 seconds	
Power Source	400 to 600 amps DC welder would be suitable to melt most alloys *500 amp DC welder optionally available	
Additional Requirements	ACCESSORIES Vacuum pump, 7 CMF Two-stage argon gas regulator Spare anodes & bushings Anodes of carbon graphite or tungsten	VOLTAGE REQUIRED 115-230
New Design & Features	Smaller in size and weight Three-way valve to easily switch between hoses and fittings Electrical box replaced with direct electrical hook-up method Water valve relocated to front for convenient control	